

Subject Index

Technical Information Papers

This document was last updated July 15, 2016

A-

Abrasion

Selection criteria for wet end ceramics, 0502-15

Abrasion resistance

Selection criteria for wet end ceramics, 0502-15

Absorption

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Acrylic fibers

see Polyacrylics, Synthetic fibers

Additives

Techniques for running “WRA” (water resistant starch adhesive), 0304-46

Adhesives

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Causes and corrections of common corrugator bonding problems, 0304-32

Evaluating glue lap adhesive properties, 0304-16

Procedure for setting up a raw material trial on the corrugator, 0304-01

Proper methods of measuring starch adhesive viscosity, 0304-33

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Starch adhesive trial, 0304-22

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Stickies definition and classification, 0603-02

Techniques for bonding of densified liners, 0304-40

Techniques for running “WRA” (water resistant starch adhesive), 0304-46

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Understanding and troubleshooting hot melt adhesives, 0304-74

Using washup water as the vehicle in starch-based corrugating adhesive, 0304-44

After dryers

Paper machine drying rate, 0404-07

Agitation

Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Agitators

Guidelines for side-entering stock agitators, 0420-13

Air

Paper machine room ventilation guidelines, 0404-50

Air balance

see Air, Materials balance

Air flow

Measurement of vacuum pump air flow, 0420-12

Minimum dryer pocket air requirements, 0404-17

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Sheet handling devices, 0404-44

Air jets

Sheet handling devices, 0404-44

Air permeability

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Air pollution

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Air staging

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Alignment

Checking the parallel of corrugating rolls with “NCR” paper, 0304-62

Alkali

Specific heat of caustic soda solutions, 0606-07

Alkaline sulfite pulping

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Alkalinity

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Ammonia

Solubility of sulfur dioxide, 0607-06

Analysis

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Angle of slide

see Slide angle

Anilox coaters

In-line coating at the corrugator, TIP 0304-39

Anilox rolls

see Flexography, Printing cylinders

Anvil

Troubleshooting the diecutting section, 0305-39

Approach flow systems

Headbox approach piping guidelines, 0404-54

Ash

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Drainage evaluation by mass measurement, 0502-12

Atmosphere

Testing atmospheres simulating end use conditions, 0808-05

Auditing

Checklist for a properly planned project, 0408-01

Automatic feeders

see Feeders

B-**Bacteria**

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Bag papers

Paper machine performance guidelines, 0404-47

Bags

Paper machine drying rate, 0404-07

Bar Width Reduction (BWR)

see Product codes

Bar codes

see Product codes

Bases

see Hydroxides

Basis weight

Headbox approach piping guidelines, 0404-54

Batch digesters

Guidelines for inspecting batch digesters, 0402-22

Batch process

Measurement of dryer condensing rates (vertical separator method), 0404-18

Beams

Calibration of flexible beam crush tester, 0304-20

Bearings

Corrugator bearing clearance checks and their impact, 0304-47

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Total indicated runout and its impact on combined board quality, 0304-56

Biocide

Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Biomass

Performance test procedure for boilers using biomass as fuel, 0416-18

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Biomechanics

see Human factors

Bisulfites

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Black liquors

Field welding of pin studs in black liquor recovery boilers, 0402-15

Recommended test procedure for black liquor evaporators, 0416-11

Recovery boiler performance calculation – short form, 0416-01

Response to contamination of high purity boiler feedwater, 0416-05

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Blade coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Bleach plants

Bleaching plant washer efficiency guide, 0606-23

Bleached board

Paper machine drying rate, 0404-07

Paper machine performance guidelines, 0404-47

Bleaching

Boiling point rise of spent sulfite liquors, 0607-21

Cotton in nonwovens, 1205-02

Chlorine gas curve, 0606-02

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of chlorine gas, 0606-03

Density of milk of lime solution, 0607-05

Energy checklist: pulp mill, 0416-24

Heat of vaporization of liquid chlorine, 0606-04

Recommended pulp bleaching stage designation method, 0606-21

Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Viscosity of liquid chlorine 0606-05

Viscosity of sodium hydroxide solutions, 0606-11

Bleaching stages

see Bleaching

Blind-drilled rolls

see Vacuum rolls

Blistering

Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17

Blow boxes

Sheet handling devices, 0404-44

Blowdown

see also Blowing

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Blowing

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Board caliper

see Thickness

Boiler feed water

see Boilers, Feedwater

Boiler tubes

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Boilers

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Explanation of recovery boiler leak indications, 0416-23

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Keys to successful chemical cleaning of boilers, 0416-06

Performance test procedure for boilers using biomass as fuel, 0416-18

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26

Bonding

Techniques for bonding of densified liners, 0304-40

Box compression

see Compression strength

Box flaps

see Flaps

Box machines

Troubleshooting a glue lap problem, 0304-10

Box plants

see Converting plants

Boxes

Corrugated boxplant-list of potential hazards, 0301-01

Critical properties to consider when unitizing, 0304-72

High vacuum sheet dewatering, 0404-60

Squaring flap cut (center special) boxes, 0305-45

Broke

Broke loss calculations, 0502-10

Bronze

Guidelines for nondestructive examination of suction roll shells, 0402-19

Weld repairs on new suction roll shells, 0402-17

Burners

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Burst testers

Calibration and maintenance of, 0304-24

Butt joints

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Butt welds

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

C-**CADCAM**

Computer-assisted machinery, 0305-02

CONEG

see Regulations

Cadmium

An explanation of the CONEG heavy metal guidelines, 0304-58

Calcination

Physical data of calcined kaolin-water suspensions, 0106-09

Calcium base liquors

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Calcium bisulfite

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Calcium carbonate

Physical data of calcium carbonate-water suspensions,

0106-01

Calcium hydroxide

Density of milk of lime solution, 0607-05

Calculations

see Computation

Calibration

Basic guidelines for image analysis measurements, 0804-09

Calibration and maintenance of the manually operated micrometer, 0304-30

Calibration of flexible beam crush tester, 0304-20

Of burst testers, 0304-24

Calibration technique for the drum style chip thickness classifier, 0602-03

Suggestions for developing a box plant quality manual, 0304-49

Caliper

see Thickness

Canadian standard freeness

Interconversion of freeness, 0809-01

Carbon steel

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Carbonates

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Physical data of calcium carbonate-water suspensions, 0106-01

Cast iron

Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14

Castings

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Caustic soda

see Sodium hydroxide

Causticizing

Energy checklist: pulp mill, 0416-24

Material balance equations relating to digester requirements, 0418-02

Ceramic coatings

Press roll cover application guidelines, 0404-37

Ceramics

Selection criteria for wet end ceramics, 0502-15

Use of ceramics on the forming section: diagnosing and preventing forming fabric wear, 0502-19

Certification

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Chalk

see Calcium carbonate

Charting

Introduction to the flow chart, 0305-26

Short-run statistical process control: a basic charting

method, 0304-70

Statistical process control pin adhesion, 0304-23

Statistical process control - procedures for charting warp, 0304-13

Checklist

see Maintenance

Chemical preparation

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Chemical properties

Chlorine dioxide (ClO₂) safe storage and handling, 0606-30

Fluoropolymer properties and applications in pulp and paper mills, 0402-37

Magnesia-base pulping solutions, 0607-04

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Chemical pulps

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Chemical recovery

Recausticizing material balance equations relating to digester requirements, 0418-02

Chemicals

Material safety data sheets, what to look for - how to understand them, 0304-38

Chests

see Stock chests

Chip classifiers

Calibration technique for the drum style chip thickness classifier, 0602-03

Chip silos

see Chip bins

Chips

Calibration technique for the drum style chip thickness classifier, 0602-03

Chlorides

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Chlorine

Chlorine gas curve, 0606-02

Density of chlorine gas, 0606-03

Heat of vaporization of liquid chlorine, 0606-04

Viscosity of liquid chlorine, 0606-05

Chlorine dioxide

Safe storage and handling of, 0606-30

Specific gravity of sodium chloride solutions, 0606-10

Chrome

Tests for corrugator roll wear, 0304-53

Chromium

An explanation of the CONEG heavy metal guidelines, 0304-58

Clad-steel plate

see Plates

Classification

Paper grade classifications, 0404-36

Clay

Kaolin clay pigment index, 0106-06

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of hydrous Kaolin-water suspensions, 0106-02

Cleaners

Catalog of stock prep pilot plants, 0502-20

Introduction to centrifugal cleaners, 0508-10

Cleaning

Cleaning anilox rolls: procedures and options, 0306-18

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Daily, weekly, and monthly maintenance checklists, 0305-34

Dryer fabric cleaning, 0404-38

Housekeeping at order and shift change and weekly, 0305-32

Introduction to centrifugal cleaners, 0508-10

Keys to successful chemical cleaning of boilers, 0416-06

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine shower recommendations, 0404-61

Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35

Cleaning chemicals

see Cleansers

Cleansers

Keys to successful chemical cleaning of boilers, 0416-06

Clogging

Nozzle maintenance and clogging, 0420-15

Clothing

see Felts, Machine clothing

Coating color

see Color

Coating thickness

Tests for corrugator roll wear, 0304-53

Coatings

Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32

Tests for corrugator roll wear, 0304-53

Coefficient of friction

see Friction factor

Combined boards

Common curtain coating problems: causes, detection, and correction, 0304-26

Obtaining off the corrugator for use in statistical process control procedures, 0304-12

Total indicated runout and its impact on combined board

quality, 0304-56

Compression

Corrugated caliper: why is it so important?, 0304-04

Compression resistance

see Compression strength

Compression strength

Corrugated caliper: why is it so important?, 0304-04

Obtaining a combined board caliper off the corrugator for use in statistical process control procedures, 0304-12

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Computation

Paper machine drying rate, 0404-07

Computer-assisted

see CAD/CAM

Concentricity

Total indicated runout and its impact on combined board quality, 0304-56

Condensates

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Measurement of dryer condensing rates (continuous method), 0404-03

Measurement of dryer condensing rates (vertical separator method), 0404-18

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Yankee dryer steam condensing rates, 0404-49

Condensation

Dryer condensing rates (batch method), 0404-02

Dryer condensing rates (continuous method), 0404-03

Condensing rates

see Condensation

Conditioning

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Testing atmospheres simulating end use conditions, 0808-05

Conductivity

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Conical refiners

Conical refining intensity, 0508-07

Consistency

Drainage evaluation by mass measurement, 0502-12

Generalized method for determining the pipe friction loss

of flowing pulp suspensions, 0410-14

Optimum for pumping pulp, 0410-15

Construction materials

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Contact bearings

see Bearings

Contact technique

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Container boards

Friction -- slide angle, 0304-34

Contaminants

see Impurities

Contamination

see Pollution control

Continuous digesters

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Contraction

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a vertical slice, 0410-02

Control charts

see Charting

Control systems

Short-run statistical process control: a basic charting method, 0304-70

Conversion factors

Units of measurement and, 0800-01

Converting factors

Moisture content of paper: terminology and conversion, 0808-02

Converting plants

Boxplant quality measurement: why test?, 0304-02

Computer-assisted machinery, 0305-02

Corrugated boxplant - list of potential hazards, 0301-01

Machinery considerations and selection, 0305-06

Copper

Role of in a printing ink, 0304-61

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Copper sulfate

Tests for corrugator roll wear, 0304-53

Cores

Determination of winder sets per reel, 0502-02

Reel diameter for various reel spool and roll core sizes, 0502-03

Corrosion

see also Corrosion inhibitors

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Estimating the first melting temperature of fireside

deposits in recovery boilers, 0416-12

Fluoropolymer properties and applications in pulp and paper mills, 0402-37

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Guidelines for inspecting batch digesters, 0402-22

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Guidelines for nondestructive examination of suction roll shells, 0402-19

Nozzle maintenance and clogging, 0420-15

Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26

Corrosion inhibitors

Keys to successful chemical cleaning of boilers, 0416-06

Corrosion prevention

Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Corrugated boards

Copper in a printing ink, 0304-61

Critical properties to consider when unitizing, 0304-72

Important quality parameters of a printing ink, 0304-59

Obtaining caliper off the corrugator for use in statistical process control procedures, 0304-12

Proofing a flexo printing ink, 0304-60

Statistical process control friction-slide angle, 0304-34

Techniques to minimize twist warp, 0304-50

Warp in corrugated board, 0304-07

Corrugated boxes

see Boxes, Corrugated boards

Corrugated containers

see Boxes, Corrugated board, Folder gluers, Die cutters

Corrugated medium

An alternative method for designating flute sizes, 0302-04

Corrugating

An alternative method for designating flute sizes, 0302-04

Corrugating adhesives

see Adhesives

Corrugating machines

Checking for coating wear on corrugating rolls, 0304-73

Checking the flute depth of corrugating rolls, 0304-75

Checking the parallel of corrugating rolls with "NCR"

paper, 0304-62

Computer-assisted machinery, 0305-02

Conducting a corrugator temperature audit, 0304-65

Corrugator bearing clearance checks and their impact, 0304-47

Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66

Improved techniques to measure corrugator glue machine meter gaps, 0304-68

Prevention of score cracking in a box plant, 0304-37

Procedure for setting up a raw material trial on the corrugator, 0304-01

Starch viscosity in corrugating adhesives, 0304-15

Tests for corrugator roll wear, 0304-53

Corrugating medium

Causes and corrections of common corrugator bonding problems, 0304-32

Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09

Paper machine performance guidelines, 0404-47

Paper machine drying rate, 0404-07

Procedure for setting up a raw material trial on the corrugator, 0304-01

Splicer defects and cures, 0304-31

Corrugating plants

see Operations

Corrugating rolls

see Rolls

Corrugator-double backer

see Corrugating machines

Corrugators

see Corrugating machines

Costs

Press section economic evaluation, 0404-22

Cotton

In nonwovens, 1205-02

Couch rolls

Paper machine vacuum selection factors, 0502-01

Counters

Counter ejector section, 0305-44

Cracks

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Guidelines for nondestructive examination of suction roll shells, 0402-19

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Crescent formers

Paper machine vacuum selection factors, 0502-01

Cross direction

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Statistical process control -- procedures for charting warp, 0304-13

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Warp in corrugated board, 0304-07

Crown

see Roll crown

Crush

Calibration of flexible beam crush tester, 0304-20

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Cubical contents

see Volumetry

Curing

Drying and curing techniques for in-line flexographic printing, 0306-06

Curtain coating

Common curtain coating problems: causes, detection, and correction, 0304-26

Weight test, 0304-19

Cutters

see Die cutters

Cutting dies

see Die cutters, Rotary machines

D-

Damage

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26

Dandy rolls

Dandy roll applications, 0404-53

Data storage

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Data tables

Moisture content of paper: terminology and conversion, 0808-02

Deaerators

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Defects

Addendum to *Corrugating Defect Terminology Manual* -- defects related to the use of fingerless singlefacers, 0304-17

Corrugator bearing clearance checks and their impact, 0304-47

Definitions

see Nomenclature

Degradation

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Densified liners

see Liners

Density

Density of aqueous sodium bicarbonate solution, 0607-13

Density of aqueous sodium carbonate solution, 0607-14

Density of chlorine gas, 0606-03

Milk of lime solution, 0607-05

Physical data of calcined kaolin-water suspensions, 0106-

09

Physical data of calcium carbonate-water suspensions,

0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-

02

Sodium sulfite solution, 0607-18

Specific gravity and density of caustic soda solutions,

0606-20

Specific gravity of sodium chloride solutions, 0606-10

Deposits

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Keys to successful chemical cleaning of boilers, 0416-06

Deterioration

see Degradation

Dewatering

see Drainage, Water removal

Diameter

Roll diameter for various reel spool and roll core sizes, 0502-03

Dictionaries

see Nomenclature

Die cutters

see also Rotary machines

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Checklist: preparing die cuts for shipment, 0305-49

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Troubleshooting the diecutting section, 0305-39

Drying and curing techniques for in-line flexographic printing, 0306-06

Introduction to flexo folder gluer/rotary diecutter TIPS, 0305-04

Minimizing rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64

Ordering cutting dies, 0305-21

Project leader, 0305-13

Proper use of pull bands, 0305-18

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Rotary cutting die maintenance, 0305-23

Rotary diecutter urethane anvil maintenance, 0305-35

Squaring flap cut (center special) boxes, 0305-45

Dieboard

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Diecut

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Differential steam pressures

see Pressure gradient

Digester balance equation

Recausticizing material balance equations relating to digester requirements, 0418-02

Digesters

Energy checklist: pulp mill, 0416-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for inspecting batch digesters, 0402-22

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Dimensional measurement

Calibration technique for the drum style chip thickness classifier, 0602-03

Dispersions

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Dissolved oxygen

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Dissolving pulps

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Doctor blades

Ink metering systems for corrugated flexo presses, 0306-09

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Documentation

Press fabric record book, 0404-21

Suggestions for developing a box plant quality manual, 0304-49

Documents

Purchase order, 0305-07

Doublefacers

Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66

Splicer defects and cures, 0304-31

Doublewall corrugated boards

Causes and corrections of common corrugator bonding problems, 0304-32

Downtime

The need for planned maintenance, 0305-30

Drainage

Drainage evaluation by mass measurement, 0502-12

Fourdrinier drainage performance evaluation – blow test method, 0410-07

High vacuum sheet dewatering, 0404-60

Interconversion of freeness, 0809-01

Drainage factor

Interconversion of freeness, 0809-01

Dry bulb temperature

Relative humidity tables, 0808-06

Dry ends

Procedure for setting up a raw material trial on the corrugator, 0304-01

Dryer bars

see Dryers

Dryer condensing rates

see Dryers

Dryer felts

see also Felts

Dryer fabric cleaning, 0404-38

Recommended tensions in dryer fabrics, 0404-04

Dryer hoods

see Exhaust hoods

Dryer pockets

Recommended minimum dryer pocket air requirements, 0404-17

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Dryer sections

Performance of, 0404-33

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Sheet handling devices, 0404-44

Dryers

Application of dryer bars, 0404-35

Dryer condensing rates (batch method), 0404-02

Dryer condensing rates (continuous method), 0404-03

Dryer condensing rates (vertical separator method), 0404-18

Dryer fabric cleaning, 0404-38

Dryer section performance monitoring, 0404-33

Dryer surface temperature measurement, 0404-39

Drying and curing techniques for in-line flexographic printing, 0306-06

Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14

Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16

High-velocity dryers, 0404-05

Inspection guidelines for Yankee hood systems, 0425-02

Paper machine drying rate, 0404-07

Papermaker's formulas, 0502-17

Press fabric record book, 0404-21

Recommended dryer differential pressures, 0404-31

Recommended minimum dryer pocket air requirements,

0404-17

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Recommended tensions in dryer fabrics, 0404-04

Steam shower applications in the forming and press section, 0404-58

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Yankee dryer steam condensing rates, 0404-49

Drying

Dryer condensing rates (continuous method), 0404-03

Dryer condensing rates (vertical separator method), 0404-18

Dryer section performance monitoring, 0404-33

Drying and curing techniques for in-line flexographic printing, 0306-06

Paper machine drying rate, 0404-07

Through drying, 0404-25

Drying rate

see Drying

Dry-laid nonwovens

Pilot paper and wet laid nonwoven machines, 0502-16

Duplex stainless steel

see Stainless steel

Dust

Paper machine room ventilation guidelines, 0404-50

E-

Economics

Press section economic evaluation, 0404-22

Economizers

Guideline specification for procurement of an economizer for a recovery boiler, 0416-21

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Edge crush tests (ECT)

Calibration of flexible beam crush tester, 0304-20

Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09

Efficiency

Paper machine performance guidelines, 0404-47

Press section monitoring, 0404-19

Recovery boiler energy efficiency improvements, 0416-16

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Elliptical technique

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Emissions

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Employee injuries

see Human factors

Energy

Energy checklist: pulp mill, 0416-24

Paper machine energy conservation, 0404-63

Recovery boiler energy efficiency improvements, 0416-16

Water treatment-related opportunities for energy

conservation in a paper mill powerhouse, 0416-13

Energy conservation

Paper machine room ventilation guidelines, 0404-50

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Enthalpy

Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08

Environmental factors

see Environments

Environments

Caustic soda (NaOH) safe storage and handling, 0606-27

Chlorine dioxide (ClO₂) safe storage and handling, 0606-30

Gaseous ozone (O₃) safe handling, 0606-28

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Methanol (CH₃OH) safe storage and handling, 0606-25

Oxygen (O₂) bulk storage and safe handling, 0606-29

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Equations

Papermaker's formulas, 0502-17

Equilibrium

Relative humidities over saturated salt solutions, 0808-03

Equipment

Starch adhesive trial, 0304-22

Quality techniques using existing equipment, 0306-11

Ergonomics

see Human factors

Erosion

Nozzle maintenance and clogging, 0420-15

Evaluation

see also Performance

Drainage evaluation by mass measurement, 0502-12

Evaporation

see also Drying

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Evaporators

Energy checklist: pulp mill, 0416-24

Recommended test procedure for black liquor evaporators, 0416-11

Exhaust gas

Paper machine room ventilation guidelines, 0404-50

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Exhaust hoods

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Extrusion coating

Guidelines for web conveyance and winding tension levels, 0200-01

F-

Fabric

See also Forming fabrics, Dryer felts

Paper machine clothing performance analysis, 0404-26

Fan pumps

Headbox approach piping guidelines, 0404-54

Feed section

see Feeding

Feedback control

see Control systems

Feeders

Material handling considerations for flexo folder gluers, 0305-54

Feedwater

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Felts

see also Press felts

Dryer fabric cleaning, 0404-38

Methods to minimize sheet rewet in the press section, 0404-59

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Press fabric record book, 0404-21

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Water permeability of press fabrics, 0404-43

Fiber length

Cotton in nonwovens, 1205-02

Fiberboards

see Boxes, Corrugated boards

Fiberglass-reinforced plastic

see Plastic

Field tests

see Test methods

Film

Guidelines for web conveyance and winding tension levels, 0200-01

Quality techniques using existing equipment, 0306-11

Filters

Paper machine room ventilation guidelines, 0404-50

Fine papers

Paper machine drying rate, 0404-07

Paper machine performance guidelines, 0404-47

Fingerless singlefacers

see Singlefacers

Fingerprints

Quality techniques using existing equipment, 0306-11

Flaps

Squaring flap cut (center special) boxes, 0305-45

Understanding and troubleshooting hot melt adhesives, 0304-74

Flat boxes

see Vacuum boxes

Flat crush tests

Calibration of flexible beam crush tester, 0304-20

Flexibility

Calibration of flexible beam crush tester, 0304-20

Flexible beam crush tester

Calibration of flexible beam crush tester, 0304-20

Flexible packaging

Guidelines for web conveyance and winding tension levels, 0200-01

Flexo folder-gluers

see Folder gluers, Die cutters, Rotary machines

Flexo ink

Printing section, 0305-38

Flexography

Cleaning anilox rolls: procedures and options, 0306-18

Guide to proper wipe roll selection for the corrugated box industry, 0306-20

Identifying anilox roll volume measuring equipment, 0306-15

Ink metering systems for corrugated flexo presses, 0306-09

Quality techniques using existing equipment, 0306-11

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Viscosity reading procedure for flexographic corrugated inks, 0304-18

Flow

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Paper machine shower recommendations, 0404-61

Flow charts

Introduction to the flow chart, 0305-26

Flow measurement

Flow determination by chemical method, 0410-09

Weirs and flumes, 0410-10

Flow rates

see Flow measurement

Flumes

Weirs and flumes, 0410-10

Fluoropolymers

Fluoropolymer properties and applications in pulp and paper mills, 0402-37

Flutes

An alternative method for designating flute sizes, 0302-04

Fogging

Steam shower applications in the forming and press section, 0404-58

Folder gluers

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Counter ejector section, 0305-44

Extruded glue mechanism supplement, 0305-43

Folding section, 0305-42

Introduction to flexo folder gluer/rotary diecutter TIPS, 0305-04

Installation, 0305-12

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Material handling considerations for flexo folder gluers, 0305-54

Computer assisted mounting systems, 0306-02

Project leader, 0305-13

Proper use of pull bands, 0305-18

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Squaring flap cut (center special) boxes, 0305-45

Folding

Folding section, 0305-42

Formaldehyde

Understanding formaldehyde management, 0304-25

Formation

Dandy roll applications, 0404-53

Forming

Forming section monitoring, 0502-14

Paper machine shower recommendations, 0404-61

Steam shower applications in the forming and press section, 0404-58

Forming fabrics

Drainage evaluation by mass measurement, 0502-12

Forming section monitoring, 0502-14

Methods to minimize sheet rewet in the press section, 0404-59

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine vacuum selection factors, 0502-01

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Use of ceramics on the forming section: diagnosing and preventing forming fabric wear, 0502-19

Water permeability of press fabrics, 0404-43

Forming sections

Fourdrinier drainage performance evaluation – blow test method, 0410-07

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Fossil fuels

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Fourdrinier machines

Control of stock activity on a fourdrinier table, 0410-08

Drainage performance evaluation – blow test method, 0410-07

Papermaker's formulas, 0502-17

Free sheet

Paper machine drying rate, 0404-07

Freeness

Interconversion of, 0809-01

Friction

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Friction factor

Statistical process control friction - slide angle, 0304-34

Fuel oil

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Furnaces

see Recovery furnaces

G-

Gas

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Gauges

see Measuring instruments

Gel temperature

see Gels

Gelatinization temperature

see Gels

Gels

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Statistical process control of starch gelatinization temperature, 0304-14

Gin notes

see Cotton

Ginning

see Cotton

Glass fibers

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Glossaries

see Nomenclature

Glue

Evaluating glue lap adhesive properties, 0304-16

Extruded glue mechanism supplement, 0305-43

Folding section, 0305-42

Glue lap

see Glued joints

Glue machine

see Gluers

Glue pattern

see Gluing

Glued joints

Troubleshooting a glue lap problem, 0304-10

Gluers

Causes and corrections of common corrugator bonding problems, 0304-32

How to prevent score cracking in a box plant, 0304-37

Improved techniques to measure corrugator glue machine meter gaps, 0304-68

Procedure for setting up a raw material trial on the corrugator, 0304-01

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Troubleshooting a glue lap problem, 0304-10

Gluing

Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17

Gluing machines

see Gluers

Grab truck

see Lift trucks

Granite

Roll material and surface requirements, 0404-41

Green liquors

Recausticizing material balance equations relating to digester requirements, 0418-02

Grinders

Grinder pulpstones – cubical contents, 0605-01

Pulpstone speed chart, 0605-02

Grinding

Granite roll material and surface requirements, 0404-41

Grooved rolls

Press roll cover application guidelines, 0404-37

Ground calcium carbonate (GCC)

see Calcium carbonate

Guides

Press fabric guiding, 0404-64

Guide rolls

Press fabric guiding, 0404-64

H-

Halogens

see specific term, e.g., Chlorine

Hardness

Response to contamination of high purity boiler feedwater, 0416-05

Water quality guidelines and monitoring requirements for

paper mill boilers operating with softened makeup water, 0416-14

Hazards

Corrugated boxplant-list of potential hazards, 0301-01

Material safety data sheets, what to look for - how to understand them, 0304-38

Hazardous materials

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Formaldehyde management, 0304-25

Material safety data sheets – what to look for, how to understand them, 0304-38

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

Understanding hazardous materials warning labels, 0304-41

Headboxes

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a vertical slice, 0410-02

Head of stock behind slice (head/jet relationships), 0410-05

Papermaker's formulas, 0502-17

Heat

Paper machine room ventilation guidelines, 0404-50

Heat content

see Enthalpy

Heat of vaporization

Liquid chlorine, 0606-04

Heat recovery

Paper machine room ventilation guidelines, 0404-50

Heat transfer

Application of dryer bars, 0404-35

Recommended test procedure for black liquor evaporators, 0416-11

Heat transfer coefficient

Recommended test procedure for black liquor evaporators, 0416-11

Heating

Conducting a corrugator temperature audit, 0304-65

Heating equipment

Steam shower applications in the forming and press section, 0404-58

Heavy metals

see Metals

High density

High density liners...what are they?, 0304-43

High density liners

see Liners

High intensity presses

Terminology for high temperature pressing, 0404-48

High performance liners

see Liners

High temperature

Terminology for high temperature pressing, 0404-48

High vacuum

High vacuum sheet dewatering, 0404-60

Hoods

Inspection guidelines for Yankee hood systems, 0425-02

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Hot melts

Understanding and troubleshooting hot melt adhesives, 0304-74

Hot pressing

Terminology for high temperature pressing, 0404-48

Housekeeping

see Maintenance, Cleaning

Humidity

Dryer section performance monitoring, 0404-33

Equilibrium relative humidities over saturated salt solutions, 0808-03

Psychrometric charts, 0404-45

Recommended minimum dryer pocket air requirements, 0404-17

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Relative humidity tables, 0808-06

Testing atmospheres simulating end use conditions, 0808-05

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Humidity measurement

Relative humidity tables, 0808-06

Humidity rooms

Paper test rooms: design considerations, 0808-04

Hydrocyclones

Introduction to centrifugal cleaners, 0508-10

Hydrogen peroxide

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Hydroxides

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Hypochlorite bleaching

see Hypochlorites, Bleaching

I-

Illumination

Basic guidelines for image analysis measurements, 0804-09

Image analysis

Basic guidelines for image analysis measurements, 0804-09

Image quality

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Impregnation

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Impulse drying

see Drying

Impurities

Dryer fabric cleaning, 0404-38

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Stickies definition and classification, 0603-02

In-process checklist

see Production

Infiltration

Paper machine room ventilation guidelines, 0404-50

Infrared detectors

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Infrared dryers

Drying and curing techniques for in-line flexographic printing, 0306-06

Ink

Copper in a printing ink, 0304-61

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Ink metering systems for corrugated flexo presses, 0306-09

Proofing a flexo printing ink, 0304-60

Quality parameters of a printing ink, 0304-59

Quality techniques using existing equipment, 0306-11

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Viscosity reading procedure for flexographic corrugated inks, 0304-18

Inorganic salts

Equilibrium relative humidities over saturated salt solutions, 0808-03

Inspection

Guidelines for inspecting batch digesters, 0402-22

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16

Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Inspection of continuous digesters and impregnation vessels, 0402-27

Inspection guidelines for Yankee hood systems, 0425-02

Nondestructive examination of suction roll shells, 0402-19

Paper machine reel-spool journals: guidelines for crack

testing and repair or replacement, 0402-34

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26

Installation

Flexo folder gluers, 0305-12

Project leader, 0305-13

Press section monitoring, 0404-19

Instruments

Forming section monitoring, 0502-14

Intensity

Conical refining intensity, 0508-07

Internal bond strength

Troubleshooting a glue lap problem, 0304-10

Iron

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

J-**Jet dryers**

Methods of evaluating high velocity dryers, 0404-05

Jet velocity

Head of stock behind slice (head/jet relationship), 0410-05

Jets

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a vertical slice, 0410-02

Joints

Troubleshooting a glue lap problem, 0304-10

Jordans

see Conical refiners

Jumbo rolls

Reel diameter for various reel spool and roll core sizes, 0502-03

K-**Kaolin**

Kaolin clay pigment index, 0106-06

Kraft papers

Paper machine drying rate, 0404-07

Kraft pulping

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

L-**Labels**

Understanding hazardous materials warning labels, 0304-41

Laboratories

Paper test rooms: design considerations, 0808-04

Laminates

Guidelines for web conveyance and winding tension levels, 0200-01

Lead

An explanation of the CONEG heavy metal guidelines, 0304-58

Leakage

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Explanation of recovery boiler leak indications, 0416-23

Lignosulfonates

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-

07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C,

0607-22

Lime mud

see White liquor mud

Lime reburning

Energy checklist: pulp mill, 0416-24

Lime-base solutions

see Calcium base liquors

Linerboards

Paper machine drying rate, 0404-07

Liners

Causes and corrections of common corrugator bonding problems, 0304-32

Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09

High density liners...what are they?, 0304-43

How to minimize rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64

Paper machine performance guidelines, 0404-47

Procedure for setting up a raw material trial on the corrugator, 0304-01

Splicer defects and cures, 0304-31

Techniques for bonding of densified liners, 0304-40

Linters

Cotton in nonwovens, 1205-02

M-

Machine clothing

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine clothing performance analysis, 0404-26

Machine direction

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Machine operation

see also Maintenance

Project leader, 0305-13

Machine rooms

Paper machine room ventilation guidelines, 0404-50

Machine speed

Pulpstone speed chart, 0605-02

Machinery

Computer-assisted machinery, 0305-02

Machinery considerations and selection, 0305-06

Project leader, 0305-13

Magnesia

see Magnesium oxide

Magnesium bisulfite

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Magnesium bisulfite liquor

see Magnesium base liquors

Magnesium oxide

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Maintenance

Burst testers, 0304-24

Calibration and maintenance of the manually operated micrometer, 0304-30

Checking for coating wear on corrugating rolls, 0304-73

Checking the flute depth of corrugating rolls, 0304-75

Checking the parallel of corrugating rolls with "NCR" paper, 0304-62

Cleaning anilox rolls: procedures and options, 0306-18

Cleanup procedures for flexo folder gluer/rotary

diecutters, 0305-33

Computer-assisted machinery, 0305-02

Counter ejector section, 0305-44

Daily, weekly, and monthly maintenance checklists, 0305-34

Extruded glue mechanism supplement, 0305-43

Field welding of pin studs in black liquor recovery boilers, 0402-15

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Housekeeping at order and shift change and weekly, 0305-32

Need for planned maintenance, 0305-30

Nozzle maintenance and clogging, 0420-15

Rotary cutting die maintenance, 0305-23

Rotary diecutter urethane anvil maintenance, 0305-35

Tests for corrugator roll wear, 0304-53

Troubleshooting a glue lap problem, 0304-10

Weld repairs on new suction roll shells, 0402-17

Management

Project leader, 0305-13

Manuals

Suggestions for developing a box plant quality manual, 0304-49

Manufacturers joints

Evaluating glue lap adhesive properties, 0304-16

Folding section, 0305-42

Go/no go gauge devices for the boxplant, 0304-42

Mass

Drainage evaluation by mass measurement, 0502-12

Material safety data sheets

see Safety

Materials

Oxygen (O₂) bulk storage and safe handling, 0606-29

Materials balance

Paper machine room ventilation guidelines, 0404-50

Materials handling

Caustic soda (NaOH) safe storage and handling, 0606-27

Gaseous ozone (O₃) safe handling, 0606-28

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Material safety data sheets – what to look for, how to understand them, 0304-38

Methanol (CH₃OH) safe storage and handling, 0606-25

Oxygen (O₂) bulk storage and safe handling, 0606-29

McKee equation

see Edge crush tests

Measurement

Conducting a corrugator temperature audit, 0304-65

Drainage evaluation by mass measurement, 0502-12

Dryer condensing rates (batch method), 0404-02

Dryer condensing rates (continuous method), 0404-03

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Units of and conversion factors, 0800-01

Utilizing statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Measuring instruments

Gauge repeatability and reproducibility study, 0304-71

Mechanical papers

Paper machine drying rate, 0404-07

Medium

see Corrugating medium

Melting point

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Mercury

CONEG heavy metal guidelines, 0304-58

Metals

An explanation of the CONEG heavy metal guidelines, 0304-58

Field welding of pin studs in black liquor recovery boilers, 0402-15

Metering equipment

Ink metering systems for corrugated flexo presses, 0306-09

Methanol

Methanol (CH₃OH) safe storage and handling, 0606-25

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

Microbes

see Bacteria

Micrometers

Calibration and maintenance of the manually operated micrometer, 0304-30

Milk of lime solution

see Calcium hydroxide

Moisture

Determination of water removal by wet presses, 0404-01

Moisture content of paper: terminology and conversion, 0808-02

Steam shower applications in the forming and press section, 0404-58

Moisture content

Determination of water removal by wet presses, 0404-01

Psychrometric charts, 0404-45

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Moisture control

Cotton in nonwovens, 1205-02

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Warp in corrugated board, 0304-07

Moisture regain

see Moisture content, Sorption

Monitoring

Press section monitoring, 0404-19

Monitors

Forming section monitoring, 0502-14

Paper test rooms: design considerations, 0808-04

Monosulfite

see Neutral sulfite pulping

Motors

Paper machine room ventilation guidelines, 0404-50

Mounting

Computer assisted mounting systems, 0306-02

Mullen

see Burst strength

Multistage process

see Bleaching

N-

Natural gas

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Needle punched

see Needling

Needling

Cotton in nonwovens, 1205-02

Neutral sulfite liquors

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

Neutral sulfite pulping

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Newsprint

Paper machine drying rate, 0404-07

Paper machine performance guidelines, 0404-47

Weight of newsprint rolls, 0502-11

Nip

Methods to minimize sheet rewet in the press section, 0404-59

Techniques for nip impressions, 0404-46

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Nip pressure
see Nip

Nitrogen oxides

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Nomenclature

Recommended pulp bleaching stage designation method, 0606-21

Retention definitions, 0402-13

Moisture content of paper: terminology and conversion, 0808-02

Sulfite pulping process, 0607-25

Terminology for high temperature pressing, 0404-48

Noncondensibles

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Nondestructive tests

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Drainage evaluation by mass measurement, 0502-12

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Inspection of continuous digesters and impregnation vessels, 0402-27

Liquid penetrant testing of new suction roll shells, 0402-11

Nondestructive examination of suction roll shells, 0402-19

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Nonwood fibers

Catalog of stock prep pilot plants, 0502-20

Nonwovens

Cotton in, 1205-02

Pilot paper and wet laid nonwoven machines, 0502-16

Nonwovens machines

Pilot paper and wet laid nonwoven machines, 0502-16

Nozzles

Nozzle maintenance and clogging, 0420-15

Paper machine shower recommendations, 0404-61

NSSC pulping

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

O-

Opacifiers

Physical data of calcium carbonate-water suspensions, 0106-01

Open time

Troubleshooting a glue lap problem, 0304-10

Openings

Measurement of vacuum pump air flow, 0420-12

Operations

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Machinery considerations and selection, 0305-06

Optical measurement

Basic guidelines for image analysis measurements, 0804-09

Optimization

Press section optimization, 0404-52

Orifices
see Openings

Osmosis

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Overfire air

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Overlays

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for inspecting batch digesters, 0402-22

Oxidation

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Oxygen

Bulk storage and safe handling of, 0606-29

Ozone

Safe handling of gaseous, 0606-28

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

P-

Packaging

CONEG heavy metal guidelines, 0304-58

Understanding and troubleshooting hot melt adhesives, 0304-74

Palletization

Checklist: preparing die cuts for shipment, 0305-49

Material handling considerations for flexo folder gluers, 0305-54

Paper

Guidelines for web conveyance and winding tension levels, 0200-01

Moisture content of paper: terminology and conversion, 0808-02

Paper grade classifications, 0404-36

Through drying, 0404-25

Paper grades

Paper grade classifications, 0404-36

Paper machines

Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14

Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16

Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01

Paper machine clothing performance analysis, 0404-26

Paper machine energy conservation, 0404-63

Paper machine performance guidelines, 0404-47

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Papermaker's formulas, 0502-17

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Pilot paper and wet laid nonwoven machines, [0502-16](#)

Press section monitoring, 0404-19

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Water permeability of press fabrics, 0404-43

Paper mills

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Fluoropolymer properties and applications in pulp and paper mills, 0402-37

Paper rolls

see Rolls, Wound rolls

Paper stock

Guidelines for side-entering stock agitators, 0420-13

Paperboard

Guidelines for web conveyance and winding tension levels, 0200-01

Papermakers alum

see Aluminum sulfate

Paraffin wax

Common curtain coating problems: causes, detection, and correction, 0304-26

Papermaking

Papermaker's formulas, 0502-17

Parallelism

see Alignment

Parameters

Paper machine performance guidelines, 0404-47

Penetrants

Liquid penetrant testing of new suction roll shells, 0402-11

Performance

Dryer section performance monitoring, 0404-33

Paper machine clothing performance analysis, 0404-26

Paper machine room ventilation guidelines, 0404-50

Press fabric record book, 0404-21

Press section economic evaluation, 0404-22

Press section optimization, 0404-52

Recovery boiler performance calculation – short form, 0416-01

Performance evaluation

Methods of evaluating high velocity dryers, 0404-05

Paper machine performance guidelines, 0404-47

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Performance tests

Performance test procedure for boilers using biomass as fuel, 0416-18

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Permeability

Water permeability of press fabrics, 0404-43

Personnel

Project leader, 0305-13

Petroleum wax

see Paraffin wax

pH

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Phosphates

Water quality and monitoring requirements for paper mill

boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Physical properties

Chlorine dioxide (ClO₂) safe storage and handling, 0606-30

Chlorine gas curve, 0606-02

Density of chlorine gas, 0606-03

Heat of vaporization of liquid chlorine, 0606-04

Magnesia-base pulping solutions, 0607-04

Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Viscosity of liquid chlorine, 0606-05

Viscosity of sodium hydroxide solutions, 0606-11

Pigment

Kaolin clay pigment index, 0106-06

Physical data of calcium carbonate-water suspensions, 0106-01

Pilot paper machines

see Paper machines

Pilot plants

Catalog of stock prep pilot plants, 0502-20

Pilot paper and wet laid nonwoven machines, 0502-16

Pin adhesion tests

Statistical process control pin adhesion, 0304-23

Pin register

see Register

Pin register mounting

see Register, Mounting

Pin studs

see Welding

Pipelines

Optimum consistency for pumping pulp, 0410-15

Piping

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Guide to the use of stainless steel pipe specifications, 0402-24

Headbox approach piping guidelines, 0404-54

Planning

Checklist for a properly planned project, 0408-01

Installation, 0305-12

Project leader, 0305-13

Plastics

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Refiner systems, their inspection and maintenance, 0508-06

Plates

see also Printing plates, Refiner disks

Conducting a corrugator temperature audit, 0304-65

Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66

Plugging

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Pocket humidity

see Humidity

Polymers

Guidelines for web conveyance and winding tension levels, 0200-01

Polyurethanes

Press roll cover application guidelines, 0404-37

Porosity

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Water permeability of press fabrics, 0404-43

Potassium

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Power plants

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Precipitated calcium carbonate (PCC)

see Calcium carbonate

Precipitators

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Prefeeder

see Feeders

Preservatives

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Press

Methods to minimize sheet rewet in the press section, 0404-59

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Press drying

see also Drying

Terminology for high temperature pressing, 0404-48

Press fabrics

Press fabric guiding, 0404-64

Dewatering and conditioning – suction box (Uhle box) design and vacuum requirements, 0404-27

Press felts

see also Felts

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Press fabric guiding, 0404-64
Press fabric record book, 0404-21
Thickness of wet press fabrics, 0404-28
Water permeability of press fabrics, 0404-43

Press rolls

Granite roll material and surface requirements, 0404-41
Press roll cover application guidelines, 0404-37
Weld repairs on new suction roll shells, 0402-17

Press sections

Determination of water removal by wet presses, 0404-01
Press section economic evaluation, 0404-22
Press section monitoring, 0404-19
Press section optimization, 0404-52
Sheet handling devices, 0404-44
Steam shower applications in the forming and press section, 0404-58
Water permeability of press fabrics, 0404-43

Presses

Papermaker's formulas, 0502-17

Pressing

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Methods to minimize sheet rewet in the press section, 0404-59

Paper machine shower recommendations, 0404-61

Pressure

Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14

Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01

Techniques for nip impressions, 0404-46

Pressure gradient

Recommended dryer differential pressures, 0404-31

Pressure roll

Paper machine vacuum selection factors, 0502-01

Preventative maintenance

see Maintenance

Print section

Printing section, 0305-38

Printing

Copper in a printing ink, 0304-61

Guide to proper wipe roll selection for the corrugated box industry, 0306-20

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Important quality parameters of a printing ink, 0304-59

In-process checklist, 0305-27

Proofing a flexo printing ink, 0304-60

Proper use of pull bands, 0305-18

Quality techniques using existing equipment, 0306-11

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Printing cylinders

Cleaning anilox rolls: procedures and options, 0306-18

Identifying anilox roll volume measuring equipment, 0306-15

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Printing ink

see Ink

Printing papers

Paper machine drying rate, 0404-07

Printing plates

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Computer assisted mounting systems, 0306-02

Quality techniques using existing equipment, 0306-11

Printing section, 0305-38

Printing proofs

Method to proof a flexo printing ink, 0304-60

Process control

Obtaining combined board caliper off the corrugator for use in statistical procedures, 0304-12

Short-run statistical process control: a basic charting method, 0304-70

Starch viscosity in corrugating adhesives, 0304-15

Statistical of starch gelatinization temperature, 0304-14

Statistical process control friction-slide angle, 0304-34

Statistical process control -- procedures for charting warp, 0304-13

Processes

In-process checklist, 0305-27

Introduction to the flow chart, 0305-26

Product codes

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Production

In-process checklist, 0305-27

Papermaker's formulas, 0502-17

Production control

In-process checklist, 0305-27

Profiles

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Steam shower applications in the forming and press section, 0404-58

Project planning

see Planning

Projects

see Planning

Protective coatings

Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32

Psychrometric charts

see also Humidity

Psychrometric charts, 0404-45

Pull collars

Troubleshooting the diecutting section, 0305-39

Pull rolls

Printing section, 0305-38

Pulp mill equipment

Guidelines for thermal spray coatings installed to prevent

corrosion in pulp mill process equipment, 0402-32

Pulp mills

Energy checklist: pulp mill, 0416-24

Fluoropolymer properties and applications in pulp and paper mills, 0402-37

Pulpers

Catalog of stock prep pilot plants, 0502-20

Pulping

Density of chlorine gas, 0606-03

Pulpstones

Grinder pulpstones: cubical contents, 0605-01

Pulpstone speed chart, 0605-02

Pulps

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Optimum consistency for pumping, 0410-15

Paper machine drying rate, 0404-07

Pilot paper and wet laid nonwoven machines, [0502-16](#)

Pumping

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Pulp, optimum consistency for, 0410-15

Pumps

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Purchase

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Purchase orders

Purchase order, 0305-07

Pyrometry

Dryer surface temperature measurement, 0404-39

Q-

Quality

Box plant quality measurement: why test?, 0304-02

Important quality parameters of a printing ink, 0304-59

Quality techniques using existing equipment, 0306-11

Starch adhesive trial, 0304-22

Suggestions for developing a box plant quality manual, 0304-49

Quality control

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Liquid penetrant testing of new suction roll shells, 0402-11

Quality manual

see Quality

R-

Radiography

Guideline for obtaining high quality radiographic testing

of butt welds in boiler tubes, 0402-33

Raw materials

Procedure for setting up a raw material trial on the corrugator, 0304-01

Recausticizing

see Causticizing

Reclaimed fibers

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Record books

see Documentation

Recovery

Energy checklist: pulp mill, 0416-24

Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26

Recovery boilers

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Explanation of recovery boiler leak indications, 0416-23

Field welding of pin studs in black liquor recovery boilers, 0402-15

Guideline specification for procurement of an economizer for a recovery boiler, 0416-21

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Recovery boiler energy efficiency improvements, 0416-16

Recovery boiler performance calculation – short form, 0416-01

Recovery boiler sootblowers: practical guidelines, 0416-20

Recovery boiler sootblowers: the basics, 0416-19

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Recovery furnaces

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Explanation of recovery boiler leak indications, 0416-23

Field welding of pin studs in black liquor recovery boilers, 0402-15

Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Recovery boiler performance calculation – short form, 0416-01

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Recycled fibers

see Reclaimed fibers

Recycled paperboard

Paper machine performance guidelines, 0404-47

Recycled papers

Paper machine performance guidelines, 0404-47

Recycling

Stickies definition and classification, 0603-02

Reels

Determination of winder sets per reel, 0502-02

Paper machine reel-spool journals: guidelines for crack

testing and repair or replacement, 0402-34

Reel diameter for various reel spool and roll core sizes, 0502-03

TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01

Refiner plates

see Refiner disks

Refiners

Catalog of stock prep pilot plants, 0502-20

Conical refining intensity, 0508-07

Refiner systems, their inspection and maintenance, 0508-06

Refining

Conical refining intensity, 0508-07

Refiner systems, their inspection and maintenance, 0508-06

Register

Computer assisted mounting systems, 0306-02

Regulating systems

see Control systems

Regulations

CONEG heavy metal guidelines, 0304-58

Relative enthalpy

see Enthalpy

Relative humidity

see Humidity

Relief

Water quality and monitoring requirements for paper mill boilers, operating on high purity feedwater, 0416-03

Removal

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Repair

see Maintenance

Repeatability

How to perform a gauge repeatability and reproducibility study, 0304-71

Reporting

Press fabric record book, 0404-21

Replacement

Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08

Reproducibility

How to perform a gauge repeatability and reproducibility study, 0304-71

Resolution

Basic guidelines for image analysis measurements, 0804-09

Retention

Definitions, 0502-13

Fourdrinier drainage performance evaluation – blow test method, 0410-07

Reverse osmosis

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Reverse warp

see Warpage

Rewetting

Methods to minimize sheet rewet in the press section, 0404-59

Rider rolls

Total indicated runout and its impact on combined board quality, 0304-56

Ring crush resistance

Techniques for bonding of densified liners, 0304-40

Ring crush tests

Calibration of flexible beam crush tester, 0304-20

Techniques for bonding of densified liners, 0304-40

Rod coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Roll coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Roll core

see Cores

Roll crown

Techniques for nip impressions, 0404-46

Roll density

see Rolls

Roll handling

see Materials handling, Jumbo rolls

Roll identification

see Rolls

Roll length

see Rolls

Roll number

see Rolls

Roll stands

Splicer defects and cures, 0304-31

Roll tracking

see Rolls

Roll weight

see Rolls

Rolling contact bearings

see Bearings

Rolling scores

see Scores

Rolls

An alternative method for designating flute sizes, 0302-04

Checking the flute depth of corrugating rolls, 0304-75

Checking for coating wear on corrugating rolls, 0304-73

Corrugator temperature audit, 0304-65

Granite roll material and surface requirements, 0404-41

Parallel of corrugating rolls with “NCR” paper, 0304-62

Press roll cover application guidelines, 0404-37

TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01

Techniques for nip impressions, 0404-46

Tests for corrugator roll wear, 0304-53

Total indicated runout and its impact on combined board quality, 0304-56

Weight of newsprint rolls, 0502-11

Rotary diecutter

see Rotary machines, Die cutters; *see also* Folder gluers

Rotary filters

Bleaching plant washer efficiency guide, 0606-23

Rotary machines

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Introduction to flexo folder gluer/rotary diecutter TIPS, 0305-04

Ordering cutting dies, 0305-21

Project leader, 0305-13

Proper use of pull bands, 0305-18

Rotary cutting die maintenance, 0305-23

Rotary diecutter urethane anvil maintenance, 0305-35

Rotation

Pulpstone speed chart, 0605-02

Roundness

see Shape

Rubbing

see also Abrasion resistance

Runnability

Sheet handling devices, 0404-44

S-**Safety**

Caustic soda (NaOH) safe storage and handling, 0606-27

Chlorine dioxide (ClO₂) safe storage and handling, 0606-

30

Corrugated boxplant-list of potential hazards, 0301-01

Gaseous ozone (O₃) safe handling, 0606-28

Hydrogen peroxide (H₂O₂) safe storage and handling,

0606-24

Material safety data sheets, 0304-38

Methanol (CH₃OH) safe storage and handling, 0606-25

Oxygen (O₂) bulk storage and safe handling, 0606-29

Sodium chlorate (NaClO₃) safe handling and storage,

0606-31

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Safety equipment

Chlorine dioxide (ClO₂) safe storage and handling, *0606-

33

Salt

see Sodium chloride

Sampling

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Saturated solutions

see Solutions

Scanners

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Scheduling

Checklist for a properly planned project, 0408-01

Housekeeping at order and shift change and weekly, 0305-32

Schopper Riegler freeness

Interconversion of freeness, 0809-01

Score breaks

How to prevent score cracking in a box plant, 0304-37

Score cracking

Troubleshooting the diecutting section, 0305-39

Score cracks

see Score breaks

Scores

Minimizing rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64

Preventing score cracking in a box plant, 0304-37

Scoring

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Screens

Catalog of stock prep pilot plants, 0502-20

Seal water

see Sealants, Water

Sealants

Guidelines for measurement of vacuum pump air flow, 0420-12

Seamless materials

Guide to the use of stainless steel pipe specifications, 0402-24

Secondary fibers

Stickies definition and classification, 0603-02

Selection

A guide to proper wipe selection for the corrugated box industry, 0306-20

Machinery considerations and selection, 0305-06

Selective catalytic reduction

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Selective noncatalytic reduction

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Semichemical pulps

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-

07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C and other temperatures, 0607-22

Sensitivity

Basic guidelines for image analysis measurements, 0804-09

Sensors

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Setting time

Understanding and troubleshooting hot melt adhesives, 0304-74

Shafts

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Shape

Total indicated runout and its impact on combined board quality, 0304-56

Sheet water content

see Moisture content

Shells

Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16

Weld repairs on new suction roll shells, 0402-17

Shipping containers

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Shock drying

Terminology for high temperature pressing, 0404-48

Showers

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine shower recommendations, 0404-61

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Steam shower applications in the forming and press section, 0404-58

Silica

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Singlefacers

Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17

Alternative method for designating flute sizes, 0302-04

Causes and corrections of common corrugator bonding problems, 0304-32

Checking for coating wear on corrugating rolls, 0304-73

Checking the flute depth of corrugating rolls, 0304-75

Parallel of corrugating rolls with “NCR” paper, 0304-62

Preventing score cracking in a box plant, 0304-37

Setting up a raw material trial on the corrugator, 0304-01

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Splicer defects and cures, 0304-31

Recommended dryer differential pressures, 0404-31

Skid

Material handling considerations for flexo folder gluers, 0305-54

Slabbing

Broke loss calculations, 0502-10

Slices

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a stock behind slice (head/jet relationship), 0410-05

Flow from a vertical slice, 0410-02

Slide angle

Statistical process control, friction, 0304-34

Slotting

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Slurry

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Slushed paper stock

see Paper stock

Smearing

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Smog

Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Sodium

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Sodium bicarbonate

Density of aqueous sodium bicarbonate solution, 0607-13

Sodium bisulfite

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Sodium borate

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Sodium carbonate

Density of aqueous sodium carbonate solution, 0607-14

Specific heat of sodium carbonate solution, 0607-15

Vapor pressure of sodium carbonate solution, 0607-16

Viscosity of sodium carbonate solution, 0607-17

Sodium chlorate

Safe storage of, 0606-31

Sodium chloride

Specific gravity of sodium chloride solutions, 0606-10

Sodium hydroxide

Caustic soda (NaOH) safe storage and handling, 0606-27

Relative enthalpy of solution, 0606-08

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Specific gravity and density of caustic soda solutions, 0606-20

Specific heat of caustic soda solutions, 0606-07

Viscosity of sodium hydroxide solutions, 0606-11

Sodium sulfite

Density of aqueous sodium sulfite solution, 0607-18

Solids content

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Solubility

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Solutions

Equilibrium relative humidities over saturated salt solutions, 0808-03

Specific heat of caustic soda solutions, 0606-07

Sorption

Cotton in nonwovens, 1205-02

Soot blowers

Recovery boiler sootblowers: practical guidelines, 0416-20

Recovery boiler sootblowers: the basics, 0416-19

SPC techniques

see Statistical methods

Specialty coating pigment

see Pigment

Specific gravity

see Density

Specific heat

Specific heat of caustic soda solutions, 0606-07

Specific heat of sodium carbonate solution, 0607-15

Specifications

Guideline specification for procurement of an economizer for a recovery boiler, 0416-21

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Speed

see Velocity

Spent sulfite liquors

Density of aqueous sodium sulfite solution, 0607-18

Splicers

Splicer defects and cures, 0304-31

Spools

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Reel diameter for various reel spool and roll core sizes, 0502-03

Spunlaced fabric

Cotton in nonwovens, 1205-02

Spray coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Squared paper

Squaring flap cut (center special) boxes, 0305-45

Squaring

see Squared papers, Trimming

Stackers

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Stacking

Corrugated caliper: why is it so important?, 0304-04

Stacking strength

see Compression strength

Stainless steel

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for nondestructive examination of suction roll shells, 0402-19

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35

Weld repairs on new suction roll shells, 0402-17

Standard conditions

Testing atmospheres simulating end use conditions, 0808-05

Starch

Proper methods of measuring starch adhesive viscosity, 0304-33

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Starch adhesive trial, 0304-22

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Using washup water as the vehicle in starch-based corrugating adhesive, 0304-44

Starch conversion

Statistical process control of starch gelatinization temperature, 0304-14

Statistical analysis

How to perform a gauge repeatability and reproducibility study, 0304-71

Obtaining combined board caliper off the corrugator for use statistical process control procedures, 0304-12

Starch viscosity in corrugating adhesives, 0304-15

Statistical distribution

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Statistical methods

Boxplant quality measurement: why test?, 0304-02

Obtaining combined board caliper off the corrugator, 0304-12

Procedures for charting warp, 0304-13

Procedures for utilizing statistical control techniques to monitor the tare weight of a run of boxes, 0304-35

Short-run statistical process control: a basic charting

method, 0304-70

Statistical process control: friction - slide angle, 0304-34

Statistical process control of starch gelatinization

temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Statistical process control pin adhesion, 0304-23

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Statistical process control

see Statistical methods

Statistical quality control

see Statistical methods

Statistics

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Obtaining combined board caliper off the corrugator for use in statistical process control procedures, 0304-12

Starch viscosity in corrugating adhesives, 0304-15

Statistical process control of starch gelatinization

temperature, 0304-14

Status reports

see Reporting

Steam

Application of dryer bars, 0404-35

Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01

Response to contamination of high purity boiler feedwater, 0416-05

Steam shower applications in the forming and press section, 0404-58

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Yankee dryer steam condensing rates, 0404-49

Steam chests

Terminology for high temperature pressing, 0404-48

Steam pressure

see Pressure gradient

Sterilization

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Stickies

Stickies definition and classification, 0603-02

Stitch bonding

Cotton in nonwovens, 1205-02

Stock flow

Optimum consistency for pumping pulp, 0410-15

Stock (pulp)

Control of stock activity on a fourdrinier table, 0410-08

Head of stock behind slice (head/jet relationships), 0410-05

Stock flow

Control of stock activity on a fourdrinier table, 0410-08

Stock preparation

Catalog of stock prep pilot plants, 0502-20

Stones

see Pulpstones

Storage

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Caustic soda (NaOH) safe storage and handling, 0606-27

Chlorine dioxide (ClO₂) safe storage and handling, 0606-30

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Methanol (CH₃OH) safe storage and handling, 0606-25

Oxygen (O₂) bulk storage and safe handling, 0606-29

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Strapping

Critical properties to consider when unitizing, 0304-72

Material handling considerations for flexo folder gluers, 0305-54

Stress

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Stress assisted corrosion

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Stress corrosion

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Strippers

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

Stripping

Troubleshooting the diecutting section, 0305-39

Stuff boxes

Headbox approach piping guidelines, 0404-54

Suction

see Vacuum

Suction press rolls

see Press rolls, Vacuum rolls

Suction presses

Paper machine vacuum selection factors, 0502-01

Suction rolls

see Vacuum rolls

Sulfite liquors

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C and other temperatures, 0607-22

Sulfite pulping

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Sulfur burner gas strength volume, 0607-01

Vapor pressure of sulfur dioxide solutions, 0607-11

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Sulfite waste liquor

see Spent sulfite liquors

Sulfur burners

Sulfur burner gas strength volume, 0607-01

Sulfur dioxide

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Sulfur burner gas strength volume, 0607-01

Vapor pressure of sulfur dioxide solutions, 0607-11

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Sulfuric acid

Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26

Supervision

Project leader, 0305-13

Surface properties

Granite roll material and surface requirements, 0404-41

Surface speed

see Retention, Machine speed

Suspended solids

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Symbols

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Systems

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

T-

Tare weight

Statistical control techniques to monitor the tare weight of a run of boxes, 0304-35

Task time

see Time

Technical nomenclature

see Nomenclature

Temperature

Conducting a corrugator temperature audit, 0304-65

Density of aqueous sodium bicarbonate solution, 0607-13

Density of aqueous sodium carbonate solution, 0607-14

Dryer section performance monitoring, 0404-33

Dryer surface temperature measurement, 0404-39

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Specific heat of sodium carbonate solution, 0607-15

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Testing atmospheres simulating end use conditions, 0808-05

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Vapor pressure of sodium carbonate solution, 0607-16

Vapor pressure of sulfur dioxide solutions, 0607-11

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

Viscosity of sodium carbonate solution, 0607-17

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Tension

Recommended tensions in dryer fabrics, 0404-04

Terminology

see Nomenclature

Test conditions

Testing atmospheres simulating end use conditions, 0808-05

Test equipment

Paper test rooms: design considerations, 0808-04

Test facilities

Paper test rooms: design considerations, 0808-04

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Test methods

Guidelines for measurement of vacuum pump air flow, 0420-12

Testing

Basic guidelines for image analysis measurements, 0804-09

Catalog of stock prep pilot plants, 0502-20

Drainage evaluation by mass measurement, 0502-12

Forming section monitoring, 0502-14

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Paper test rooms: design considerations, 0808-04

Recommended test procedure for black liquor evaporators, 0416-11

Water removal by wet presses, 0404-01

Thermal measurement

Recovery boiler performance calculation – short form, 0416-01

Thermal spray

Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32

Guidelines for inspecting batch digesters, 0402-22

Thermobonding

Cotton in nonwovens, 1205-02

Thermography

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Thermoplastics

Fluoropolymer properties and applications in pulp and paper mills, 0402-37

Thick stock

see High consistency

Thickness

Corrugated caliper: why is it so important?, 0304-04

Method for evaluating thickness of wet press fabrics, 0404-28

Obtaining combined board caliper off the corrugator for use in statistical process control procedures, 0304-12

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Through drying

Through drying, 0404-25

Tissue

Inspection guidelines for Yankee hood systems, 0425-02

Pilot paper and wet laid nonwoven machines, [0502-16](#)

Tolerance

Corrugator bearing clearance checks and their impact, 0304-47

Total indicated runout

see also Combined boards

Total indicated runout and its impact on combined board quality, 0304-56

Total reduced sulfur

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Transport

Checklist: preparing die cuts for shipment, 0305-49

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Trim

Broke loss calculations, 0502-10

Paper machine room ventilation guidelines, 0404-50

Trimming

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Squaring flap cut (center special) boxes, 0305-45

Troubleshooting

Forming section monitoring, 0502-14

Glue lap problem, 0304-10

Press section monitoring, 0404-19

Recommended test procedure for black liquor evaporators, 0416-11

Steam shower applications in the forming and press section, 0404-58

Tubes

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Keys to successful chemical cleaning of boilers, 0416-06

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Tungsten carbide

Tests for corrugator roll wear, 0304-53

Tuning

see Control

Turpentine

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Twisting

Techniques to minimize twist warp, 0304-50

U-

Uhle boxes

See also Vacuum boxes

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Ultrafine ground limestone

see Limestone

Ultraviolet radiation

Drying and curing techniques for in-line flexographic printing, 0306-06

Ultrasonic tests

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Guidelines for inspecting batch digesters, 0402-22

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Unitized handling

Critical properties to consider when unitizing, 0304-72

Units of measurement

Units of measurement and conversion factors, 0800-01

Unloading

Sodium chlorate (NaClO₃) safe handling and storage, 0606-31

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

U.P.C.

see Product codes

Urethanes

Rotary diecutter urethane anvil maintenance, 0305-35

V-**Vacuum**

High vacuum sheet dewatering, 0404-60

Paper machine vacuum selection factors, 0502-01

Papermaker's formulas, 0502-17

Steam shower applications in the forming and press section, 0404-58

Vacuum boxes

High vacuum sheet dewatering, 0404-60

Paper machine vacuum selection factors, 0502-01

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Vacuum equipment

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements, 0404-27

Vacuum filters

Bleaching plant washer efficiency guide, 0606-23

Vacuum pumps

Guidelines for measurement of vacuum pump air flow, 0420-12

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Vacuum rolls

Guidelines for nondestructive examination of suction roll shells, 0402-19

Liquid penetrant testing of new suction roll shells, 0402-11

Paper machine vacuum selection factors, 0502-01

Press roll cover application guidelines, 0404-37

Techniques for nip impressions, 0404-46

Weld repairs on new suction roll shells, 0402-17

Vacuum washers

Bleaching plant washer efficiency guide, 0606-23

Valves

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Headbox approach piping guidelines, 0404-54

Vapor pressure

Chlorine gas curve, 0606-02

Vapor pressure of sulfur dioxide solutions, 0607-11

Vapor pressure of sodium carbonate solution, 0607-16

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Variance

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Varnish

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Velocity

see also Machine speed

Pulpstone speed chart, 0605-02

Ventilation

Paper machine room ventilation guidelines, 0404-50

Recommended minimum dryer pocket air requirements, 0404-17

Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24

Viscosity

Density of aqueous sodium sulfite solution, 0607-18

Liquid chlorine, 0606-05

Proper methods of measuring starch adhesive viscosity, 0304-33

Quality techniques using existing equipment, 0306-11

Statistical process control of starch viscosity, 0304-15

Viscosities of spent sulfite liquors at 26.7° C (Oswalt capillary viscometer), 0607-22

Viscosity of a neutral sulfite spent liquor (Oswalt capillary viscometer), 0607-23

Viscosity of sodium carbonate solution, 0607-17

Viscosity of sodium hydroxide solutions, 0606-11

Viscosity reading procedure for flexographic corrugated inks, 0304-18

Vision

Basic guidelines for image analysis measurements, 0804-09

Volume

Grinder pulpstones – cubical contents, 0605-01

Identifying anilox volume measuring equipment, 0306-15

W-**Warning labels**

see Hazardous materials

Warpage

Go/no go gauge devices for the boxplant, 0304-42

Statistical process control -- procedures for charting warp,

0304-13

Techniques to minimize twist warp, 0304-50

Warp in corrugated board, 0304-07

Wash waters

Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Washers

Energy checklist: pulp mill, 0416-24

Bleaching plant washer efficiency guide, 0606-23

Washing

Bleaching plant washer efficiency guide, 0606-23

Recommended pulp bleaching stage designation method, 0606-21

Wastewater treatment equipment

see Effluent treatment

Water

see also Solubility

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Guidelines for measurement of vacuum pump air flow, 0420-12

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Water content

see Moisture content

Water hardness

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water permeability

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Water removal

Determination of water removal by wet presses, 0404-01

High vacuum sheet dewatering, 0404-60

Methods to minimize sheet rewet in the press section, 0404-59

Paper machine drying rate, 0404-07

Water resistance

Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Water treatment

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Water vapor

Paper machine room ventilation guidelines, 0404-50

Waterside cracking

Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38

Wax

Common curtain coating problems: causes, detection, and correction, 0304-26

Curtain coating weight test, 0304-19

Wear resistance

see Abrasion resistance

Web tension

Guidelines for web conveyance and winding tension levels, 0200-01

Webs

see also Paper webs

Guidelines for web conveyance and winding tension levels, 0200-01

Weight

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Procedure for utilizing statistical control techniques to monitor the tare weight of a run of boxes, 0304-35

Weight of newsprint rolls, 0502-11

Weirs

Weirs and flumes, 0410-10

Welding

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Field welding of pin studs in black liquor recovery boilers, 0402-15

Wet bulb temperature

Relative humidity tables, 0808-06

Wet ends

Drainage evaluation by mass measurement, 0502-12

Forming section monitoring, 0502-14

How to prevent score cracking in a box plant, 0304-37

Selection criteria for wet end ceramics, 0502-15

Wet felts

see also Felts

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Wet presses

Determination of water removal by, 0404-01

Wet pressing

Terminology for high temperature pressing, 0404-48

Wet strength

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Wet-laid nonwovens

Pilot paper and wet laid nonwoven machines, [0502-16](#)

White liquors

Recausticizing material balance equations relating to

digester requirements, 0418-02

White water

Drainage evaluation by mass measurement, 0502-12

Flow determination by chemical method, 0410-09

Weirs and flumes, 0410-10

Width

Weight of newsprint rolls, 0502-11

Winding

Guidelines for web conveyance and winding tension levels, 0200-01

Wire

Use of ceramics on the forming section: diagnosing and preventing forming fabric wear, 0502-19

Williams freeness

Interconversion of freeness, 0809-01

Winders

Determination of winder sets per reel, 0502-02

Wiperoll

see Flexography

Wood

Calibration technique for the drum style chip thickness classifier, 0602-03

Wood chips

see Chips

Wood containing papers

see Mechanical papers

Wood free papers

Paper machine drying rate, 0404-07

Work place

see Human factors

Working conditions

see Environments

Wound rolls

Reel diameter for various reel spool and roll core sizes, 0502-03

TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01

Writing papers

Paper machine drying rate, 0404-07

X-Y-Z-

Yankee cylinders

see Yankee dryers

Yankee dryers

Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01

Inspection guidelines for Yankee hood systems, 0425-02

Techniques for nip impressions, 0404-46

Yankee dryer steam condensing rates, 0404-49